Date:

Wednesday, 3/26/2008 1:46:25 PM

User:

Kim Johnston

Process Sheet

Customer

: CU-DAR001 Dart Helicopters Services

Drawing Name

: R/H LOW PROFILE BASKET BASE ASS'Y

Job Number

: 38217

Estimate Number

: 13171

P.O. Number

: 3/26/2008

Part Number

: D3712042

This Issue Prsht Rev.

: NC

S.O. No. : **Drawing Number** : D3712 REVB

First Issue

Project Number

: //

: LARGE FAB ASSY Type

Drawing Revision

: N/A : B

: 37525 Previous Run

Material

Written By

Checked & Approved By

: 4/16/2008 Due Date

Qty:

1 Um: Each

Comment

: Est Rev:A new issue

08-01-30

DD verified by:EC

ecn 1145 08-03-19 DD verified by: Est Rev:B chg to revB

Additional Product

Job Number: · .~.



Seq. #:

Machine Or Operation:

Description:

1.0

M304TS0750W065

304 SQ Tube.75x.75x.065W



Comment: Qty.:

44.7920 f(s)/Unit

Total: 44.7920 f(s)

304 SQ Tube.75x.75x.065W

2.1- Cut Ribs as per dwg from 3/4" x 3/4" x 0.065 wall 304/316 SS tubing. PART NUMBER

QTY 2

D3726-1

BATCH M1075014

2

D3727-1

M107514

2

D3734-1 D3735-1 M107514 M107514

3

6

D3739-1

M107514

3 D3740-1

2- deburr

2.0

D23273

Spacer Bushing



Comment: Qty.:

Total:

2.0000 Each(s)

2.0000 Each(s)/Unit Spacer Bushing

batch

3.0

D2581

Mounting Bracket

Comment: Qty.:

2.0000 Each(s)/Unit

Mounting Bracket batch 33 7248 Total:

2.0000 Each(s)

Dart Aerospace Ltd

W/O:		1	WORK ORDER	CHANGES					
DATE	STEP	PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		·							
		-							
		•							
		· · · · · · · · · · · · · · · · · · ·							
Part No):	PAR #:	Fault Category:	NCR:	Yes	No DQ	A:	_ Date: _	
					QA: I	N/C Close	d:	Date:	

NCR:		WORK ORDER NON-CONFORMANCE (NCR)									
		Description of NC		Corrective Action Section B	Verification	Approval					
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector			
						1					
		•									
	-	•									

Wednesday, 3/26/2008 1:46:25 PM Date: User: Kim Johnston **Process Sheet** Drawing Name: R/H LOW PROFILE BASKET BASE ASS'Y Customer: CU-DAR001 Dart Helicopters Services Part Number: D3712042 Job Number: 38217 Job Number: Seq. #: Description: **Machine Or Operation:** D37251 HOOP 4.0 Comment: Qty.: Total: 2.0000 Each(s) 2.0000 Each(s)/Unit HOOP batch 1 HINGE HALF 5.0 3.0000 Each(s) Comment: Qty.: 3.0000 Each(s)/Unit Total: HINGE HALF batch_B3 6.0 Comment: Qty.: 5.0000 Each(s)/Unit Total: 5.0000 Each(s) Basket Hoop Batch: <u>B376/</u> D37591 BUSHING 7.0 Total: 21.0000 Each(s) Comment: Qty.: 21.0000 Each(s)/Unit **BUSHING** batch 33760 LARGE FABRICATION RESOURCE 1 LARGE FAB 8.0 Comment: LARGE FABRICATION RESOURCE 1 * 1- take D3166-1 and trim as per dwg D3746 to make D3746-1, D3746-3, D3746-5 and D3746-7 2- take D3746-3, D3746-5, D3746-7 and drill holes as per dwg D3746 - - - 08 03 31 3- drill holes in both D3727-1 as per dwg D3727 -4- drill holes in D3735-3 as per dwg D3735 5- deburr 6- assemble as per dwg D3712 and weld as per QSI004

Dart Aerospace Ltd

W /O:		WORK ORDER CHANGES										
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspecto					
Part No:		PAR #: Fault Category:	NCR: Yes No DQA:				1					
			QA: I	N/C Close	d:	Date: _						

NCR:		WORK ORDER NON-CONFORMANCE (NCR)									
		Description of NC		Corrective Action Section B		Verification	Annroyal				
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector			
				~							
			,,,								
				t.							
				-							

Wednesday, 3/26/2008 1:46:25 PM Date: User: Kim Johnston **Process Sheet** Drawing Name: R/H LOW PROFILE BASKET BASE ASS'Y Customer: CU-DAR001 Dart Helicopters Services Part Number: D3712042 Job Number: 38217 Job Number: Description: Seq. #: Machine Or Operation: Expanded Metal Flat Stai 9.0 M304EX07516F 39.9000 sf(s) Comment: Qtv.: 39.9000 sf(s)/Unit Total: Expanded Metal Flat Stainless Steel Pick: Part Number Description Batch Qty M167514 38sq.ft M304EX0.75-16F **Expanded Metal** LARGE FABRICATION RESOUR 10.0 Comment: LARGE FABRICATION RESOURCE 1 1- cut mesh to fit inside basket base and sides as per dwg D3744 and D3745 (COS-82 2- weld mesh as per dwg D3712 TO CURRENT STEP 11.0 QC5 Comment: INSPECT WORK TO CURRENT STEP VISUAL WELDING INSPECTION 12.0 QC9 Comment: VISUAL WELDING INSPECTION POWDER COATING 13.0 u 107550 Comment: POWDER COATING Powder Coat White Gloss (Ref: 4.3.5.2) as per QSI 005 4.3 14.0 QC3 Comment: INSPEC COAT/CHEMICAL CONVERSION PACKAGING RESOURCE #1 PACKAGING 1 15.0 Comment: PACKAGING RESOURCE #1 Pick Packing Kit

Dart Aerospace Ltd

W/O:			WORK ORDER	CHANGES	······································				
DATE	STEP	PROCEDURE CHANGE				Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspecto
Part No		PAR #:	Fault Category:	NCR:	Yes	No DQ	A:	Date:	
					QA: N	I/C Close	d:	_ Date: _	
NCR:		V	VORK ORDER NON-CON	FORMANCE	(NCF	R)			45
		Dagarinting of NO	Corrective Action	n Section B					

NCR:		WORK ORDER NON-CONFORMANCE (NCR)									
		Description of NC		Corrective Action Section B				A			
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Approval Chief Eng	Approval QC Inspector			
•	;										
	1 1				l .	1					

Wednesday, 3/26/2008 1:46:25 PM Date: User: Kim Johnston **Process Sheet** Drawing Name: R/H LOW PROFILE BASKET BASE ASS'Y Customer: CU-DAR001 Dart Helicopters Services Job Number: 38217 Part Number: D3712042 Job Number: Description: Seq. #: **Machine Or Operation:** 16.0 D2931 Bumper 2.0000 Each(s) 2.0000 Each(s)/Unit Total: Comment: Qty.: Bumper Bolt 17.0 AN311A Comment: Qty.: Total: 6.0000 Each(s) 6.0000 Each(s)/Unit Bolt 14820 18.0 AN960JD8 Washer Comment: Qty.: 2.0000 Each(s) Total: 2.0000 Each(s)/Unit Washer 19.0 AN960JD10 Washer 12.0000 Each(s) Comment: Qtv.: 12.0000 Each(s)/Unit Total: Washer 20.0 MS20600AD4W3 Comment: Qty.: 2.0000 Each(s) 2.0000 Each(s)/Unit Total: Cherry Rivets M1807 MS21042L3 21.0 Comment: Qty.: 6.0000 Each(s) 6.0000 Each(s)/Unit Total: M 106883 Nut SMALL & MEDIUM FAB RESOURCE 1 SMALL FAB 1 22.0 Comment: Assemble as per dwg D3712 QC5 INSPECT WORK TO CURRENT STEP 23.0 Comment: INSPECT WORK TO CURRENT STEP 2 x D3757-1 8 380-8 ×

Dart Ae	rospace	Ltd							
W/O:			W	ORK ORDER CHANGE	S				
DATE	STEP	PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			ANI -						
Part No	:	PAR #:	Fault Cate	gory:	NCR: Yes	No DQA:		Date:	
			·					Date:	
NCR:			WORK ORD	ER NON-CONFORMAN	CE (NCR)			
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Section Action Description Chief Eng	Sign & Date	Verifica Section		Approval Chief Eng	Approval QC Inspector
			4						
1									

Wednesday, 3/26/2008 1:46:25 PM Date: Kim Johnston User: **Process Sheet** Drawing Name: R/H LOW PROFILE BASKET BASE ASS'Y Customer: CU-DAR001 Dart Helicopters Services Job Number: 38217 Part Number: D3712042 Job Number: Description: Seq. #: Machine Or Operation: PACKAGING RESOURCE #1 24.0 PACKAGING 1 Comment: PACKAGING RESOURCE #1 Identify and Sto Location: FINAL INSPECTION/W/O RELEASE 25.0 QC21 Comment: FINAL INSPECTION/W/O RELEASE 08-04-16 Job Completion

Dart Ae	rospace	Ltd								
W/O:			W	ORK ORDER CH	ANGES	***				
DATE	STEP	PRO	OCEDURE CH	ANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
							•.			
Part No	:	PAR #:	Fault Cat	egory:	NCF					
NCR:		\	WORK ORI	DER NON-CONFO	RMANCE			a:	_ Date:	
		Description of NC		Corrective Action	Section B		Verific	ation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Descrip Chief Eng		Sign & Date	Section		Chief Eng	QC Inspector
	1									

-041	-042	PART NUMBER	DESCRIPTION	
х	1	D3712-041	BASKET BASE ASSEMBLY	
`	Х	D3712-042	BASKET BASE ASSEMBLY	
2	2	D2327-3	SPACER BUSHING	
2	2	D2581	MOUNTING BRACKET	
2	2	D2931	BUMPER	
2	2	D3725-1	НООР	7
2	2	D3726-1	RIB	
2	2	D3727-1	RIB	
2	2	D3734-1	RIB	
5	5	D3735-1	RIB	
1	1	D3735-3	RIB	
3	3	D3739-1	RIB	
3	3	D3740-1	RIB	
1	1	D3744-1	MESH	
1	1	D3746-1	RIB	
1	1	D3746-3	RIB	
2	2	D3746-5	RIB	¬ •••
1	1	D3746-7	RIB	
3	3	D3748-1	HINGE HALF	
2	2	D3757-1	BLANKING PLATE	
21	21	D3759-1	BUSHING	
6	6	AND 440	0017	
2	2	AN3-11A AN960JD8	BOLT	
12	12	AN960JD10	WASHER	
-			WASHER	
	6	MS20600AD4W3 MS21042L3	RIVET NUT	
6				

NOTES:
1) MATERIAL: NONE
2) FINISH: POWDER COAT GLOSS WHITE (4.3.5.2) PER DART QSI 005 4.3
3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
4) UNITS: INCHES UNLESS OTHERWISE NOTED
5) BREAK SHARP EDGES: N/A
6) IDENTIFICATION: N/A
7) WEIGHT: N/A
8) WELDING: PER DART QSI 004
9) MASK ALL HOLES PRIOR TO POWDER COATING.

SHOP COPY
RETURN TO
RETURN TO
RETURN TO
RETURN TO
RETURN TO
ROPY
UNCONTROLLED COPY
U

В	ADDED ADDED D2 AN3	DOMPER & HA 2 ZONE C2 OT DETAIL H. SH MESH TRIMM 111A BOLT WA DINGLY.	SLA	08.02.22				
Α	NEW IS	SUE		AJS	08.01.29			
REV.			BY	DATE				
DESIG	N	AJS	DART AEROSPACE LTD					
DRAW	N	ĄJS	HAWKESBURY, ONTAR					
CHECK	ŒD	LE	DRAWING NO.		REV. B			
MFG. A	APPR.	77	D3712		SHEET 1 OF 4			
APPRO	OVED	148	TITLE		SCALE			
DE AP	DE APPR.		BASKET BASE ASSY	NTS				
DATE	08.0	12 22	COPYRIGHT © 2008 BY DART AEROSPACE LTD THO DOCUMENT IS PRIMATE AND COMPOSITION, AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS					

С

2

8





